IMPORTANT SAFETY RECALL

DEWALT DC920, DC930, DC935, DC936, DC940 Individual Cordless Drills

DEWALT Industrial Tool Company is recalling to repair the following 12 Volt, 14.4 Volt, 18 Volt Heavy-Duty XRP™ Individual Cordless Drills. The trigger switch could over-heat which presents a possible risk of fire.

The following drills may be affected:		
Model Number	Description	Date Codes
DC920	Heavy-Duty XRP™ 1/2" (13mm) 18 Volt Cordless Drill/Driver	200723 through 200741
DC930	Heavy-Duty XRP™ 1/2" (13mm) 14.4 Volt Cordless Drill/Driver	200625 through 200746
DC935	Heavy-Duty XRP™ 1/2" (13mm) 14.4 Volt Cordless Hammerdrill/Drill/Driver	200627 through 200746
DC936	Heavy-Duty XRP™ 1/2" (13mm) 14.4 Volt Cordless Hammerdrill/Drill/Driver	200635 through 200746
DC940	Heavy-Duty XRP™ 1/2" (13mm) 12 Volt Cordless Drill/Driver	200635 through 200746

ONLY DRILLS WITH THE MODEL NUMBERS AND DATE CODES LISTED ABOVE ARE AFFECTED.

The location of the model number and date code are shown on the photography below.
Products stamped with an "M" following the date code have been repaired and are not affected.

Model Number Identification

Date Code Identification



Repaired or Not Affected



If your drill is affected, **STOP USING IT IMMEDIATELY,** and call DEWALT toll-free at

1-888-742-9168

between 8:00 a.m. and 5:00 p.m., Eastern Time, Monday through Friday, or go to

www.DEWALT.com

for the location of a service center to obtain a free inspection and repair, if necessary.

Recall done in cooperation with U.S. Consumer Product Safety Commission 12/07 CORDLESSRCP

Post Until April 30, 2008