

SAFETY RECALL


PITTSBURGH AUTOMOTIVE PNEUMATIC ROLLER SEAT (select models)

IN CERTAIN UNITS, THE CONNECTION FROM THE SEAT TO THE SEAT POST CAN BREAK, PRESENTING A FALL HAZARD.

STOP USING THESE SEATS IMMEDIATELY AND CHECK TO SEE IF YOUR SEAT IS INCLUDED IN THE RECALL USING THE INFORMATION BELOW. IF IT IS INCLUDED, RETURN TO YOUR LOCAL HARBOR FREIGHT TOOLS RETAIL STORE FOR A CHOICE OF A REPLACEMENT SEAT OR A GIFT CARD REFUND.

The seats are red with a 15”- 20” pneumatic lift range, and have a black storage tray located above the wheels. The warning label located on the topside of the storage tray shows the Item # and the white label on the underside of the tray shows the Product Registration No. CA-44417. Only roller seats with the following item and accompanying UPC numbers are included in the recall:

Item Number:	UPC:
61896	792363618960
46319	193175340764
63456	792363634564



Affected seats were sold at Harbor Freight Tools retail locations nationwide from July 2014 through Sept. 2021. For more information, or for return by mail instructions, call Harbor Freight Tools at **(800) 444-3353** Monday through Friday between 8 a.m. and 4:30 p.m. PT, or email recall@harborfreight.com.