

ITEM 58829

BRAUN™

4 FT. LED T8 FLUORESCENT TUBE REPLACEMENT

1800 LUMENS

DIRECT SWAP

COMPATIBILITY CHART



MANUFACTURER	MODEL NUMBER	1 LAMP FIXTURE	2 LAMP FIXTURE	3 LAMP FIXTURE	4 LAMP FIXTURE
GE	GE332MAX-G-N	-	-	Compatible	-
	GE132MAXP-N/ULTRA	Compatible	-	-	-
	GE259MAX-G-N	-	Compatible	-	-
	GE259MAX-G-N-DIYB	-	Compatible	-	-
	GE332MAX-G-L	-	-	Compatible	-
	GE432MAXP-L/ULTRA	-	-	-	Compatible
	GE232MAXP-N/ULTRA	-	Compatible	-	-
PHILIPS	IOP-2P32-N	-	Compatible	-	-
	ICN-1P32-N	Compatible	-	-	-
	IOP-4P32-N	-	-	Compatible	Compatible
	IOP-2P59-N	-	Compatible	-	-
	ICN-4P32-N	-	-	-	Compatible
	REB-2P32-N	-	Compatible	-	-
HOWARD	EP2/32IS/MV/MC/HE	-	Compatible	-	-
	EPL3/32IS/MV/SC/HE	-	-	Compatible	-
	EP3/32IS/MV/MC/HE	-	-	Compatible	-
	EPL2/32IS/MV/MC/HE	-	Compatible	-	-
TCP	E3P32ISUNVE	-	-	Compatible	-
KEYSTONE	KTEB-232-UV-IS-N-P	-	Compatible	-	-
	KTEB-332-UV-IS-N-P	-	-	Compatible	-
OSRAM	OSRAM QHE 4X32T8/UNV ISL-SC	-	-	-	Compatible
	OSRAM QHE 2X32T8/UNV ISN-SC	-	Compatible	-	-
	OSRAM QTP 3X32T8/UNV ISN-SC	-	-	Compatible	-
	OSRAM QTP 2X32T8/UNV ISN-SC	-	Compatible	-	-
	OSRAM QTP 4X32T8/UNV ISN-SC	-	-	-	Compatible
	OSRAM QHE 2X59T8/UNV ISL-SC	-	-	-	Compatible
ROBERTSON	IEA432T8120N	-	-	-	Compatible
	ISU232T8120	-	Compatible	-	-
ACT	ACT2P32ISUNVE	-	Compatible	-	-
SUNLITE	40155-SU.SB/232/MV	-	Compatible	-	-
TRIAD	B232IUNVHE-N	-	Compatible	-	-
	B332IUNVHE-A	-	-	Compatible	-

GE	GE232MAX-G-H	Non-Compatible			
	GE432MAX-G-N	Non-Compatible			
	GE332MAXP-H/ULTRA	Non-Compatible			
	GE232MVP-N-V03	Non-Compatible			
	GE232MAX-L/ULTRA	Non-Compatible			
	GE332MAX-G-H	Non-Compatible			
	GE232MAXP-H/ULTRA	Non-Compatible			
	GE332MAXP-H/ULTRA	Non-Compatible			
	GE432MAXP-H/ULTRA	Non-Compatible			
PHILIPS	IOPA-3P32-N	Non-Compatible			
	IOPA-3P32-LW-N	Non-Compatible			
	IOP-3P32-N	Non-Compatible			
	IOP-4PSP32-SC	Non-Compatible			
	REB-4P32-SC	Non-Compatible			
	IOPA-2P32-N	Non-Compatible			
HOWARD	EPH4/32IS/MV/SC/HE	Non-Compatible			
TCP	E4P32ISUNVE	Non-Compatible			
	E4P32ISUNVHE	Non-Compatible			
WORKHORSE	WHSG1-UNV-T8-IS	Non-Compatible			
	WHSG4-UNV-T8-IS	Non-Compatible			
Robertson	ISL432T8HEMV	Non-Compatible			